

HVOF APPLIED COATING - Corrosion Resistance

Internal Test - This Sample Piece Was Submerged In The Chesapeake Bay For Over One Year. The Base Material Is Carbon Steel And The Pipe Is Corroding From The Inside Out.

